



Recreational Educational Camp Inspection Report

Establishment Information	
Facility Name CAMP LUTHER INC	Facility Type Recreational/Educational Camp (RRE)
Facility ID # SYOG-7QRVR2	Facility Telephone # 715 546-3647
Facility Address	
Licensee Name CAMP LUTHER INC	Licensee Address

Inspection Information		
Inspection Type Routine	Inspection Date July 6, 2021	Total Time Spent

Equipment Temperatures	
Description	Temperature (Fahrenheit)
Hoshizaki reach in	35
Walk in	36
Traulsen reach in	32
Us cooler Lower level walk in	40
walk in freezer kllpekk	-11

Food Temperatures	
Description	Temperature (Fahrenheit)
Ranch dressing in Hoshizaki	36
Mashed potatoes in walk in	38
Delivered chocolate milk	38
Milk in traulsen	38
yogurt in lower level walk in	41

Warewashing Info					
Machine Name	Sanitization Method	Thermo Label	PPM	Sanitizer Name	Sanitizer Type
Dish washer		180		hot water	heat sanitizing
Quat bucket			150	heavy duty quat	ammonia

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations
Total # 2
<p style="color: blue; margin: 0;">Good Retail Practices - 51 - Plumbing installed proper backflow devices</p> <p style="color: blue; margin: 0;">This is a Critical violation</p> <p>OBSERVATION: An air break but no air gap provided on food prep sink. Due to water on the ground when food prep sink was draining, plumbing was modified to provide an air break. An air gap needs to be provided for food prep sinks. Kitchen manager is currently using a colander to wash and prep foods. See photo attached</p> <p>CORRECTIVE ACTION(S): Provide an air gap on water supply side to protect water supply. Contact a licensed plumber to troubleshoot why water is not properly draining from the food prep sink. Correct By: 20-Jul-2021</p> <p>CODE CITATION: 5-202.13 An air gap between the water supply inlet and the flood level rim of the PLUMBING FIXTURE, EQUIPMENT, or nonFOOD EQUIPMENT shall comply with the State Uniform Plumbing Code, chs. SPS 381 to 387, as enforced by the Wisconsin department of safety and professional services. [P]Note: Contact the Safety and Building Division at the department of safety and professional services, P.O. Box 2509, Madison, WI 53701, telephone 608-266-3151 and 711 (TTY) or http://dsps.wi.gov/sb/SB-HomePage.html.</p>

OBSERVATION: In The Tower and The Fort staff sleeping rooms, no guard rails are installed on the bunk beds to prevent occupants from rolling out.

CORRECTIVE ACTION(S): Install guard rails on all the bunk beds. Correct By: 16-Jul-2021

CODE CITATION: ATCP 78.21 (4) BUNK BEDS. When campers sleep in upper bunks, guardrails shall be installed to prevent occupants from rolling out. The top of the rail shall be at least 5 inches above the top of the mattress and the bottom of the rail shall be no more than 3.5 inches above the top of the bed frame. No more than 2 beds may be stacked vertically and there shall be a vertical separation of at least 2.5 feet measured from the top of the lower mattress to the bottom of the frame of the upper bed. A free space of at least 2.5 feet shall be provided above the mattress of the upper bed.

Comments:

Certified Food Manager: Alexander Morris Exp 11.29.22

Approx. 110 campers per week, 19 staff with direct camper supervision, 12 Lifeguards

Ensure the counselor sleeping room/ area of The Fort (cabin) is provided with a smoke detector on both the womens and mens side. A wall was recently installed in between the two areas, and there is not a detector on one of the sides.

NOTE: Heat strip used for hot water dish machine tests water temperature, not contact surface temperature. Purchase irreversible heat label stickers that adhere to the dish to ensure the surface of the dish is reaching at least 160 degrees (sanitizing temperature). (Heat strip reached a water temperature of 180 degrees during inspection)



Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Covid 19

Sanitarian

Handwritten signature of Jody McKinney R.S.

Jody McKinney
(715) 369-6226